



PACIFIC MARINE SERVICES

APPR No : PMS/S.IWS.P/002/UAE

Date : 06TH JUN 2016

Pages : One (1)

Statement of Initial Approval

Issued within the scope of the Pacific Marine Services
General Conditions

Approval of the Carrying out In-Water Surveys of Ships
and mobile offshore units.

Name of Company : AMASCO L.L.C

Address : Ahmed Ali Maintenance - Al Jadaf – P.O.Box 8618 – Dubai . UAE

This is to certify that:

The undersigned Surveyor of the P.M.S. acting within the Pacific Marine Services Division General Conditions. has performed at the Service Supplier's request, an assessment of the facilities, organizational structure and procedures of the Service Supplier in compliance with the relevant requirements.

The facilities, organizational structure and procedures were found satisfactory for the servicing of the equipment as described in the Schedule of approval .

SCHEDULE OF THE APPROVAL :

1- Description of approval : Perform in-water surveys, in lieu of periodical bottom survey in drydock.

2- Technical Data / Application :

- The above company is approved to assist P.M.S at In-Water Surveys according to the Pacific Marine Services Rules on ships and equipment classed to the Society and on ships and equipment, for which PMS is authorized.
- Divers action is restricted to operation according to the instructions of P.M.S surveyor or other authorized representative of P.M.S.
- Rules for the safety of divers and equipment are not included in this approval.
- Rather, the responsibility for the safety of such resting with the employing Company.
- In event of changes being made to the equipment, the Certificate continues to be valid only, if modifications were checked in accordance with the requirements for approval.

3- The continued validity of this approval subject to satisfactory audit.

This Initial of approval is valid until⁴ 05TH June 2018

Issued at AJMAN the 06TH day of June 2016

For the pacific marine services

Capt , Mohammed .A. Jumahh
Technical Manager

This Certificate may be cancelled if :

- ¹ The service provided has been improperly carried out or the results improperly reported.
- ² The surveyor has found any deficiencies in the accepted operating systems of the service supplier.
- ³ The firm has failed to inform of any major changes having effect on the quality of the service rendered.